


3~380 V  
50 Hz

green&yellow wire is ground/earth wire,when connect with fixed line,it must be equipped with full disconnect device

黄绿双色线为接地线，连接固定线路必须装有全极断开装置！

HKN-30SN2V/40SN2V/50SN2V



- 8. motor
- 7. thermal overload relay
- 6. limit switch
- 5. A.C. conductor
- 4. start button
- 3. stop button
- 2. timer
- 1. external power wire

与机架及所有易触及金属部件可靠连接

is reliable to connect with frame and all accessible metal part

3~380V：定时控制，过载保护。

timing control, overload protection

8	电机	YD100L-8/4P	1台	
7	热过载继电器	LRD-10N	2只	4~6A
6	行程开关	JLXK1-411	1只	
5	交流接触器	LC1-D1210 Q7 N /LADN22 C	3只	线圈电压 ~380V
4	启动按钮	LAY3	3只	绿色
3	停止按钮	LAY3	1只	红色
2	定时器	DS30	1只	
1	外接电源线	YZW 300/500V	2m	4x1.5
序号	名称	规格 型号	数量	备注

电气原理图

双速双动和面机

标记	页数	更改文件号	签字	日期
设计			标准	
校对			审定	
审核				