



# WARING COMMERCIAL

Europe **TORq 2.0** Blender  
with Electronic Keypad & Timer

## TBB160E



Date Code Location  
YY|MM|DD  
year year | month month | day day

Illustration#	Part#	Description
1	028769-E	Eastman Jar Lid Cover
2	035238-V	Vinyl Jar Lid
3	035465	Blending Assembly (with O ring and bearing holder nut)
4	035239	48 oz. Stackable Container ONLY
5	035885 035091	Jar Pad ( <i>changed after 6/20/2018</i> ) Jar Pad (use 035885)
6	035085	Hole Plug (4 required)
7	034275	Sems (4 required)
8	034273	B Gasket (4 required)
9	037034 035251	Drive Coupling ( <i>on units after 11/15/2019</i> ) Drive Coupling
10	037033	Coupling Washer ( <i>on units after 11/15/2019</i> )
11	503609 503460-160-E	Top Housing with Badge ( <i>on units after 9/28/2022</i> ) Top Housing Assembly
12	035234	Control Housing Front Bezel ( <i>on units after 9/28/2022</i> )
13	035253	LED Lens
14	035165	TBB160 230 volt Control Panel
15	034900	PCB Cushion (4 required)
16	013604	Washer (4 required <i>as of 11/15/2019</i> 2 required)
17	034904	Rubber Grommet (4 required)
18	034902	Sems (4 required)
19	035894	Control Board Bracket
20	035237	Control Housing Back Bezel ( <i>on units after 9/28/2022</i> )
21	035090	Screw (4 required)
22	038576	Top Housing Control Seal ( <i>on units after 9/28/2022</i> )
23	034272	A Gasket (4 required)
24	034274	Screw (4 required)
25	035816	Chiaphua Motor No Sensor
26	012409	Small Crimp Connectors (3 required <i>on units after 7/3/2018</i> - 2 required)
	019123	Large Crimp Connector (2 required <i>on units after 7/3/2018</i> - 3 required)
27	013731	Cable Ties (8 required)
28	503483	Motor Housing with Dampeners
29	017948	Europe Cord
30	033619	Strain Relief
31	503480 035079	Bottom Housing Assembly with Feet Bottom Housing

Illustration#	Part#	Description
32	034274	Screw (4 required)
33	035088	Foot (4 required)

**Part No Longer Used**

(last used 10/10/2019)



035237

Control Housing Back Bezel

