


# WARING COMMERCIAL

Europe **TORq 2.0** Blender  
with 2 Toggle Switches

## TBB145E



**035871**  
Control Panel Overlay

**503482**  
Container with Blending Assembly

Date Code Location  
YY|MM|DD  
year year month month day day

Illustration#	Part#	Description
1	028769-E	Eastman Jar Lid Cover
2	035238-V	Vinyl Jar Lid
3	035465	Blending Assembly Kit
4	035239	48 oz. Stackable Container ONLY
5	035885 035091	Jar Pad ( <i>changed after 7/6/2018</i> ) Jar Pad (use 035885)
6	035085	Hole Plug (4 required)
7	034275	Sems (4 required)
8	034273	B Gasket (4 required)
9	037034 035251	Drive Goupling ( <i>on units after 11/15/2019</i> ) Drive Coupling
10	037033	Coupling Washer ( <i>on units after 11/15/2019</i> )
11	503609 503460-145-E	Top Housing Assembly with Badge ( <i>on units after 9/28/2022</i> ) Top Housing Assembly
12	035080	Control Housing Front Bezel ( <i>on units after 9/28/2022</i> )
13	038576	Housing Control Seal ( <i>on units after 9/28/2022</i> )
14	035083	Back Bezel ( <i>on units after 9/28/2022</i> )
15	035090	Screw (2 required)
16	035253	LED Lens
17	035163	TBB145 230 volt Control Panel Assembly
18	035255	Washer (2 required)
19	035089	Screw (2 required)
20	034900	PCB Cushion (2 required)
21	013604	Washer (2 required)
22	034904	Rubber Grommet (4 required)
23	034902	Sems (4 required)
24	035894	Control Board Bracket
25	034272	A Gasket (4 required)
26	034274	Screw (4 required)
27	035816 035475	Chiaphua Motor No Sensor ( <i>on units after 2/26/2018</i> ) ECM Motor
28	503483	Motor Housing with Dampeners
29	012409 019123	Small Crimp Connectors (2 required) Large Crimp Connector (3 required)

2022)

Illustration#	Part#	Description
30	013731	Cable Ties (6 required)
31	017948	Cordset
32	033619	Strain Relief
33	503480 035079	Bottom Housing Assembly with Feet Bottom Housing
34	034274	Screw (4 required)
35	035088	Foot (4 required)

